



C = slaglengd

Öll mál önnur en gengjumál eru í mm

Stærð tjakks mm	AM	B	CH	CH2	D	DD	E	EE	KK	L	L0	L1	L2	SW	TG	VD	WH	ZM
32	22	30	8	17	12	M6	50	1/8"	M10x1.25	120	94	69	19.0	10	32.5	10.5	26	146
40	24	35	8	19	16	M6	55	1/4"	M12x1.5	135	105	87	21.5	13	38.0	11.0	30	165
50	32	40	12	24	20	M8	68	1/4"	M16x1.5	143	106	82	28.5	17	46.5	12.5	37	180
63	32	45	12	24	20	M8	79	3/8"	M16x1.5	158	121	93	28.5	17	56.5	12.5	37	195
80	40	45	14	30	25	M10	98	3/8"	M20x1.5	174	128	90	34.0	22	72.0	17.0	46	220
100	40	55	14	30	25	M10	115	1/2"	M20x1.5	189	138	100	37.5	22	89.0	17.0	51	240